

Ship out 07

Work Order ID 136901

136901

Page 1

Item ID: DSI 9053-011

Accept

N1900040100

Setup Start

NS1

Revision ID:

Item Name: Basket Hinge Kit

Stop

NS2

Start Date: 9/17/15 Start Qty: 4.00

4

Cust Item ID:

Required Date: 10/22/15 Req'd Qty: 4.00

4

Customer:

Reference:

Approvals:

Process Plan:

Date: 15.9.16

Tooling:

Date:

Run Start

NR1

QC:

Date:

SPC (Y/N):

Date:

Stop

NR2

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
DSI 9053	Rev 15.09.27	5.0							
100	Document Control	0.00							
100	DOCUMENT CONTROL								
DC	Memo	0.00							
Doc.Control -USB or Paperwork	Photocopy bluefile and create labels as per PPP DSI 9053-011 CHG001								
									DAS 02 9-89 SEP 28 2015
110	Pick Kit	0.00							
110									
Packaging	Memo	0.00							
Packaging									
									DAS 27 9-89 SEP 23 2015
120	QC4- 100% Inspect kits for completeness	0.00							
120									
QC	Memo	0.00							
Quality Control									
									DAS 02 9-89 SEP 28 2015

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By _____ Lead hand / Supervisor Approval Verification _____ QC / QA Coordinator Approval _____		
Description Work Order Deviation				Disposition					

Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐				FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
				OTHER : _____							

Work Order ID 136901***136901***

Page 2

Item ID: DSI 9053-011

Accept

N900040100Setup Start ***NS1***

Revision ID:

Item Name: Basket Hinge Kit

Stop ***NS2***Start Date: 9/17/15 Start Qty: 4.00 ***4***

Cust Item ID:

Required Date: 10/22/15 Req'd Qty: 4.00 ***4***

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start ***NR1***

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130	Packaging	0.00							DAS 02 9-89
130									
Packaging	Memo	0.00							
Packaging	Identify and pack for shipping as per PPP Dsi9053-011 Location: FG123_								
	PPP Rev: <u>66 123</u>								SEP 28 2015
140	QC21- Final Inspection - Work Order Release	0.00							
140									
QC	Memo	0.00							MCS SEP 28 2015
Quality Control									

MCS SEP 28 2015

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					

Root Cause				FAULT CATEGORY							
Environment	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐	Power Loss/Surge	☐	Positioned Wrong	☐
Design	☐	Operator	☐	Bending	☐	Set-up	☐	Folio/Program	☐	Outside Dimensions	☐
Doc/Data	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐	Grain	☐	Over/Under tolerance	☐
Equip/Tooling	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Part Incorrect	☐
Handling/Pre	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐	Wrong Stock Pulled	☐	Part Lost/Missing	☐
Material	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐	Out of Sequence	☐	Part Moved	☐
Internal Transport	☐	Poor Information	☐	Crushing	☐	Countersink	☐	Off-set	☐	Drawing	☐
Tribal Knowledge	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐	Mislabeled	☐	Finish	☐
LOA	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐	Fit/Function	☐	Misread	☐
Substation	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐	Misaligned/off center	☐	Turning Sequence	☐
Past Expiry Date	☐	Manufacturing Process	☐	OTHER :							
Misidentified	☐	Past Due	☐								

Picklist Print

Wednesday, September 16, 2015 4:04:12 PM

Page 1

Work Order ID: 136901

136901

Parent Item: DSI 9053-011

DSI 9053-011

Parent Item Name: Basket Hinge Kit

Start Date: 9/17/15

Required Date: 10/22/15

Start Qty: 4.00

Required Qty: 4.00

Comments: IPP Rev:A02.05.15New IssueNG

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
MS21042L4		Purchased	No			110	Each	1,754.000	2	8			Dr 26 9-89
MS21042L4									**				DAS
Locknut													27
		DAS											9-89
		02											
		9-89											

Location	Loc Qty	Loc Code
FP001	2	
m124231	2	
GA	112	
m127813	112	
ST260a	170	
m130799	56	
m131803	6	
m132262	108	
ST305	1470	
m128300	8	
m130388	7	
m130922	97	
m131618	12	
m132123	56	
m132382	1290	

AN3-12A

Purchased

No

120

Each

68.0000

4

16

AN3-12A

Bolt

DAS
02
9-89

DAS
27
9-89

SEP 24 2015

Location	Loc Qty	Loc Code
GA	34	
m129682	34	
ST349	34	
m133064	34	

DAS
28
9-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					

Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐				FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
				OTHER : _____							

Picklist Print

Wednesday, September 16, 2015 4:04:12 PM

Page 2

Work Order ID: 136901

Parent Item: DSI 9053-011

Parent Item Name: Basket Hinge Kit

136901

DSI 9053-011

Start Date: 9/17/15

Required Date: 10/22/15

Start Qty: 4.00

Required Qty: 4.00

AN3-14A

Purchased

No

120

Each

114.0000

6

24

AN3-14A

Bolt

DAS
02
9-89

**

Location

Loc Qty

Loc Code

ST338a

100

m132825

100

ST348

14

m132680

14

AN4-6A

Purchased

No

120

Each

279.0000

2

8

AN4-6A

BOLT

DAS
02
9-89

**

Location

Loc Qty

Loc Code

CA

143

M128403

43

M130851

100

ST345

136

M128403

8

M131153

128

D2232-1

Manufactured

No

120

Each

9.0000

2

8

D2232-1

Basket Hinge

DAS
02
9-89

**

Location

Loc Qty

Loc Code

WA004

9

105333

7

105885

2

DAS
27
9-89

SEP 23 2015

DAS
27
9-89

SEP 24 2015

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
							Completed By		
							Lead hand / Supervisor Approval Verification		
							QC / QA Coordinator Approval		

Root Cause				FAULT CATEGORY			
Environment ☐	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐
Design ☐	☐	Operator	☐	Bending	☐	Set-up	☐
Doc/Data ☐	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐
Equip/Tooling ☐	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐
Handling/Pre ☐	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐
Material ☐	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐
Internal Transport ☐	☐	Poor Information	☐	Crushing	☐	Countersink	☐
Tribal Knowledge ☐	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐
LOA ☐	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐
Substation ☐	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐
Past Expiry Date ☐	☐	Manufacturing Process	☐	OTHER : _____			
Misidentified ☐	☐	Past Due	☐				

Picklist Print

Wednesday, September 16, 2015 4:04:12 PM

Page 3

Work Order ID: 136901

136901

Parent Item: DSI 9053-011

DSI 9053-011

Parent Item Name: Basket Hinge Kit

Start Date: 9/17/15

Required Date: 10/22/15

Start Qty: 4.00

Required Qty: 4.00

D2232-3

Manufactured No

120

Each

26.0000

2

8

D2232-3

Basket Hinge

DAS
02
9-89

**

DAS
27
9-89

DAS
26
9-89

Location

Loc Qty

Loc Code

WA004

26

115847

20

132731

6

6
2
40

MS21042L3

Purchased

No

120

Each

1,133.000

10

40

MS21042L3

Nut

DAS
02
9-89

**

DAS
27
9-89

DAS
26
9-89

Location

Loc Qty

Loc Code

FP001

334

M130922

334

GA

181

M131317

181

ST305

618

116549

12

126333

49

M128754

2

M132123

17

M132382

2

M132883

17

M132930

11

M133134

508

40

SEP 23 2015

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					

Root Cause				FAULT CATEGORY			
Environment ☐		No Re-verification ☐		Pressure/Forced ☐		Temperature/Cure ☐	
Design ☐		Operator ☐		Bending ☐		Set-up ☐	
Doc/Data ☐		Offset/Setup ☐		Centre Not Concentric ☐		BOM/Route ☐	
Equip/Tooling ☐		Supplier ☐		Cracks ☐		Broken/Damage/Defect ☐	
Handling/Pre ☐		Training ☐		Crimp/Kink/Ripple/Wave ☐		Inspection Incomplete/Unqualified ☐	
Material ☐		Use for Testing ☐		Cuffs ☐		Contamination ☐	
Internal Transport ☐		Poor Information ☐		Crushing ☐		Countersink ☐	
Tribal Knowledge ☐		Rushing ☐		Heat Treat ☐		Cut Too Short ☐	
LOA ☐		Product Improvement ☐		Wave/Twist in Tube ☐		Instructions Incomplete/Unclear ☐	
Substation ☐		Process Improvement ☐		Marks/Chatter ☐		Drill Holes ☐	
Past Expiry Date ☐		Manufacturing Process ☐		OTHER : _____			
Misidentified ☐		Past Due ☐					

Picklist Print

Wednesday, September 16, 2015 4:04:12 PM

Work Order ID: 136901

Parent Item: DSI 9053-011

Parent Item Name: Basket Hinge Kit

136901

DSI 9053-011

Start Date: 9/17/15

Start Qty: 4.00

Requ

Requ

NAS1149D0363J

Purchased

No

120

Each

1,463.000

40

160

NAS1149D0363.I

Washer

DAS
02
9-89

Location

Loc Qty

Loc Code

CA	246
m130799	246
GA	248
m130799	248
ST269	969
m126319	7
m131618	1
m132317	10
m132677	50
m133031	901

**

DAS
26
9-89

NAS1149D0463J

Purchased

No

120

Each

2,623.000

8

32

NAS1149D0463.I

WASHER

AS
12
9-89

Location

Loc Qty

Loc Code

GA	41
M129390	41
ST260a	1000
M133077	1000
ST269	1582
M129682	86
M130799	371
M132035	112
M132317	125
M132677	888

**

DAS
26
9-89

DAS
27
9-89

SEP 23 2015

32

Wednesday, September 16, 2015 4:04:12 PM

Shop Packet Print

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By _____ Lead hand / Supervisor Approval Verification _____ QC / QA Coordinator Approval _____		
Description Work Order Deviation				Disposition					

Root Cause				FAULT CATEGORY			
Environment ☐	☐	No Re-verification ☐	☐	Pressure/Forced ☐	☐	Temperature/Cure ☐	☐
Design ☐	☐	Operator ☐	☐	Bending ☐	☐	Set-up ☐	☐
Doc/Data ☐	☐	Offset/Setup ☐	☐	Centre Not Concentric ☐	☐	BOM/Route ☐	☐
Equip/Tooling ☐	☐	Supplier ☐	☐	Cracks ☐	☐	Broken/Damage/Defect ☐	☐
Handling/Pre ☐	☐	Training ☐	☐	Crimp/Kink/Ripple/Wave ☐	☐	Inspection Incomplete/Unqualified ☐	☐
Material ☐	☐	Use for Testing ☐	☐	Cuffs ☐	☐	Contamination ☐	☐
Internal Transport ☐	☐	Poor Information ☐	☐	Crushing ☐	☐	Countersink ☐	☐
Tribal Knowledge ☐	☐	Rushing ☐	☐	Heat Treat ☐	☐	Cut Too Short ☐	☐
LOA ☐	☐	Product Improvement ☐	☐	Wave/Twist in Tube ☐	☐	Instructions Incomplete/Unclear ☐	☐
Substation ☐	☐	Process Improvement ☐	☐	Marks/Chatter ☐	☐	Drill Holes ☐	☐
Past Expiry Date ☐	☐	Manufacturing Process ☐	☐	OTHER : _____			
Misidentified ☐	☐	Past Due ☐	☐				

SUPERCEDED BY

D205-541 REV. E

SUPERCEDED BY

D350-607 REV. F

DESIGN UP	DRAWN BY UP	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED #	APPROVED #	DRAWING NO. DSI 9053	REV. B SHEET 1 OF 2
DATE 01.04.16		TITLE BASKET HINGE CHANGE SCALE NTS	
A	96.11.06	NEW ISSUE	
B	01.04.16	REDRAWN	

DART

DART SERVICE INSTRUCTION

TO AMEND INSTALLATION DRAWING D205-541 REV. D
(REF. CANADIAN STC: SH96-120, FAA STC: SR00696NY)
AND INSTALLATION DRAWING D350-607 REV. E
(REF. CANADIAN STC: SH94-14, FAA STC: SR00213NY)

IF THE D2569 HINGE IS BEING REPLACED, THE PARTS LIST OF D205-541 REV. D (D205-541-011 CHG 003) / D350-607 REV. E (D350-607-041/-042 CHG 004) SHOULD BE AMENDED AS FOLLOWS:

REPLACE:

Qty	Part Number	Description
1	D2569	HINGE
36	AD64ABSLF	RIVET

WITH:

Qty	Part Number	Description
X	DSI 9053-011	HINGE CHANGE KIT
2	D2232-1	HINGE PLATE
2	D2232-3	HINGE PLATE
4	AN3-12A	BOLT
6	AN3-14A	BOLT
2	AN4-6A	BOLT
40	AN960JD10	WASHER*
8	AN960JD416	WASHER*
10	MS21042L3	NUT (OR MS21042-3)
2	MS21042L4	NUT (OR MS21042-4)

* NOTE: IT IS ALSO ACCEPTABLE TO REPLACE THE WASHERS THAT ARE USED AS SPACERS WITH A SINGLE ALUMINUM SPACER OF APPROPRIATE LENGTH (SEE PAGE 2).

REPLACE D2569 HINGE AS FOLLOWS:

- 1) REMOVE EXISTING HINGE BY DRILLING OUT AD64ABSLF RIVETS. PLUG HOLES WITH RIVETS IF DESIRED.
- 2) DRILL HOLES IN D2232-1/-3 HINGE PLATES AS SHOWN ON PAGE 2.
- 3) LOCATE D2232-1 HINGE PLATE ON D2512 BASKET LID ASSEMBLY. REMOVE MESH AS REQUIRED SO THAT D2232-1 HINGE PLATE SITS FLUSH ON D2512 BASKET LID ASSEMBLY. TRANSFER DRILL Ø0.191 HOLES. INSTALL D2232-1 HINGE PLATE WITH HARDWARE AS SHOWN ON PAGE 2. REPEAT AT OTHER END OF BASKET.
- 4) LOCATE POSITION OF D2232-3 HINGE PLATE FROM D2232-1 HINGE PLATE BY ENSURING Ø0.257 HOLE IS ALIGNED. REMOVE MESH AS REQUIRED TO ENSURE THAT D2232-3 HINGE PLATE AND ATTACHMENT HARDWARE SITS FLUSH AGAINST D2206/D2221 BASKET BASE ASSEMBLY. TRANSFER DRILL Ø0.191 HOLES. INSTALL D2232-3 HINGE PLATE WITH HARDWARE AS SHOWN ON PAGE 2. REPEAT AT OTHER END OF BASKET.
- 5) TOUCH UP PAINT AS REQUIRED.


Copyright © 1996 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.



SUPERCEDED BY
0205-544 Rev. E
SUPERCEDED BY
0350-601 Rev. F

DESIGN	AP	DRAWN BY	AP	DART AEROSPACE LTD HAMMERSBURY, ONTARIO, CANADA
CHECKED	AP	APPROVED	AP	REV. B
DATE	01.04.16	DRAWING NO.	DSI 9053	SHEET 2 OF 2
TITLE	BASKET HINGE CHANGE	SCALE	NTS	



Sheet 07

Work Order ID 136901

136901

Wednesday, September 16, 2015 4:04:08 PM

Page 1

Item ID: DSI 9053-011

Accept

Revision ID:

N9000040100

Setup Start *NS1*

Item Name: Basket Hinge Kit

Stop *NS2*

Start Date: 9/17/15 Start Qty: 4.00

4


Cust Item ID:

Required Date: 10/22/15 Req'd Qty: 4.00

4

Customer:

Reference:

Approvals: Process Plan:  Date: 15.9.16

Tooling:

Date:

Run Start *NR1*

QC: Date:

SPC (Y/N):

Date:

Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
----------	--------------

DSI 9053	Rev N/A
----------	---------

100

Document Control

0.00

100

DOCUMENT CONTROL


DC

Memo

0.00

Doc. Control - USB or Paperwork

Photocopy bluefile and create labels as per PPP DSI 9053-011 CHG001

ML5
SEP 17 2015


110

Pick Kit

0.00

110

Packaging

Memo

0.00

Packaging

120

QC4- 100% Inspect kits for completeness

0.00

120

QC

Memo

0.00

Quality Control

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS <table style="width: 100%; border: none;"> <tr> <td style="border: none;">Skid-tube ☐</td> <td style="border: none;">Cross tube ☐</td> <td style="border: none;">Water Jet ☐</td> <td style="border: none;">Engineering ☐</td> </tr> <tr> <td style="border: none;">Machining ☐</td> <td style="border: none;">Small Fab ☐</td> <td style="border: none;">Prod. Eng. Coord. ☐</td> <td style="border: none;">Quality ☐</td> </tr> <tr> <td style="border: none;">Thermoforming ☐</td> <td style="border: none;">Finishing ☐</td> <td style="border: none;">Rec/Store/Packaging ☐</td> <td style="border: none;">Other ☐</td> </tr> <tr> <td style="border: none;">Large Fab ☐</td> <td style="border: none;">Composite ☐</td> <td style="border: none;">Supplier ☐</td> <td></td> </tr> </table>						Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐																						
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐																						
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐																						
Large Fab ☐	Composite ☐	Supplier ☐																							
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval																		
Description Work Order Deviation				Disposition			Completed By																		
							Lead hand / Supervisor Approval Verification																		
							QC / QA Coordinator Approval																		
Root Cause		FAULT CATEGORY																							
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐	OTHER : ☐																			

SUPERCEDED BY

D205-541 Rev. E

SUPERCEDED BY

D350-607 Rev. F



DESIGN UP	DRAWN BY UP	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED #	APPROVED #	DRAWING NO. DSI 9053	REV. B SHEET 1 OF 2
DATE 01.04.16		TITLE BASKET HINGE CHANGE	SCALE NTS
A	96.11.06	NEW ISSUE	
B	01.04.16	REDRAWN	

DART SERVICE INSTRUCTION

TO AMEND INSTALLATION DRAWING D205-541 REV. D
(REF. CANADIAN STC: SH96-120, FAA STC: SR00696NY)
AND INSTALLATION DRAWING D350-607 REV. E
(REF. CANADIAN STC: SH94-14, FAA STC: SR00213NY)

IF THE D2569 HINGE IS BEING REPLACED, THE PARTS LIST OF D205-541 REV. D (D205-541-011 CHG 003) / D350-607 REV. E (D350-607-041/-042 CHG 004) SHOULD BE AMENDED AS FOLLOWS:

REPLACE:

Qty	Part Number	Description
1	D2569	HINGE
36	AD64ABSLF	RIVET

WITH:

Qty	Part Number	Description
X	DSI 9053-011	HINGE CHANGE KIT
2	D2232-1	HINGE PLATE
2	D2232-3	HINGE PLATE
4	AN3-12A	BOLT
6	AN3-14A	BOLT
2	AN4-6A	BOLT
40	AN960JD10	WASHER*
8	AN960JD416	WASHER*
10	MS21042L3	NUT (OR MS21042-3)
2	MS21042L4	NUT (OR MS21042-4)

* NOTE: IT IS ALSO ACCEPTABLE TO REPLACE THE WASHERS THAT ARE USED AS SPACERS WITH A SINGLE ALUMINUM SPACER OF APPROPRIATE LENGTH (SEE PAGE 2).

REPLACE D2569 HINGE AS FOLLOWS:

- 1) REMOVE EXISTING HINGE BY DRILLING OUT AD64ABSLF RIVETS. PLUG HOLES WITH RIVETS IF DESIRED.
- 2) DRILL HOLES IN D2232-1/-3 HINGE PLATES AS SHOWN ON PAGE 2.
- 3) LOCATE D2232-1 HINGE PLATE ON D2512 BASKET LID ASSEMBLY. REMOVE MESH AS REQUIRED SO THAT D2232-1 HINGE PLATE SITS FLUSH ON D2512 BASKET LID ASSEMBLY. TRANSFER DRILL Ø0.191 HOLES. INSTALL D2232-1 HINGE PLATE WITH HARDWARE AS SHOWN ON PAGE 2. REPEAT AT OTHER END OF BASKET.
- 4) LOCATE POSITION OF D2232-3 HINGE PLATE FROM D2232-1 HINGE PLATE BY ENSURING Ø0.257 HOLE IS ALIGNED. REMOVE MESH AS REQUIRED TO ENSURE THAT D2232-3 HINGE PLATE AND ATTACHMENT HARDWARE SITS FLUSH AGAINST D2206/D2221 BASKET BASE ASSEMBLY. TRANSFER DRILL Ø0.191 HOLES. INSTALL D2232-3 HINGE PLATE WITH HARDWARE AS SHOWN ON PAGE 2. REPEAT AT OTHER END OF BASKET.
- 5) TOUCH UP PAINT AS REQUIRED.

Copyright © 1996 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.